

MURRAY

Chris-Craft

SPORTBOATS, INC.


 XXXXXXXXXXXXXXXXXXXX  
 XXXXXXXXXXXXXXXXXXXX  
 1818 768 1718

 REMIT TO:  
 MURRAY BOAT ADMINISTRATIVE  
 SERVICES INC.  
 DRAWER CS 19053  
 ATLANTA, GEORGIA 30384-8008

INVOICE

 CREDIT NO.  
 S.O.D. 10

 003341  
 SKYLINE'S ANCHORAGE YCT BASIN

 74 E EAU BALLIE CAUSEWAY  
 MELBOURNE FL 32937

 INVOICE NO. 034412-11  
 INVOICE DATE 09/20/85

 FINANCED  
 BY

 NAPLES FEDERAL BANK  
 5801 PELICAN BAY BLVD.  
 NAPLES, FL 33941

SHIP TO:

 HULL #  
 ENGINE #  
 DECK #  
 FINISH #

 AN85777  
 0880497  
 1932946

 SHIPPER  
 EBON

 MURRAY C+C SPORTBOATS, INC.  
 SARASOTA FL 33555

DATE	ITEM	QUANTITY	UNIT	PRICE	TOTAL
7/22/85	1986 Y-1	DLR H78	09/20/85	TRUCK	FLOOR PL

QTY.	PART NUMBER	DESCRIPTION	LIST PRICE	DISC.	NET
1	0266AC-0080	W/290 MERCURIDER	3499.00	25	2629.75
1	0266AC-5633	STONE, ALCOHOL/ELECTRIC	245.00	25	183.75
1	0266AC-5013	REFRIG 115/12V W/BATT & ISOL	790.00	25	592.50
1	0266AC-4601	PROP. MERC ALUMINUM - std	0.00	0	0.00
1	0266AC-5377	COLOR BERMIE - TAUPE/BROWN	0.00	0	0.00
1	0266AC-5692	NTR. PRESSURE-HOT/COLD W/SHOWER	1285.00	25	963.75
1	0266AC-0621	CANVAS, RPT	210.00	25	157.50
1	0266AC-1088	CUSHION, V-BERTH FILLER	140.00	25	105.00
1	0266AC-1241	DRINKERIES	245.00	25	183.75
1	0266AC-6120	HOUR METER	90.00	25	67.50
1	0266AC-5759	RECTIFIER, BATTERY CHARGER 12V	465.00	25	348.75
1	0266AC-5563	SEAT, APT BENCH BROWN	345.00	25	258.75
1	0266AC-5683	SKIN PLATFORM, FIBERGLASS BROWN	745.00	25	558.75
1	0266AC-5900	TOP, FOLDING W/SIDE CURTAINS	390.00	25	292.50
1	0266AC-6771	WINDSHIELD WIPER	110.00	25	82.50
1	0266AC-6802	WIRING, BOCKSIDE W/SHORE, CABLE	495.00	25	371.25

THIS ORDER REPLACES ORDER #4164

GROSS TOTAL			30410.00
1	DEALER	3574.00	FRT - C&C
1	MARK	2726.00	240.00
			0.00

 NO. NAME, ADDRESS, PHONE NO.  
 SALES PERSON, PHONE NO.  
 ORDER OR TO WHOM TO SEND

CUSTOMER SERVICE

TOTAL DUE 30650.00

ORIGINAL LIMITED WARRANTY REGISTRATION CERTIFICATE

266-627

I have received a copy of and have read the Murray Chris-Craft Cruisers, Inc., the Murray Chris-Craft Sportboats, Inc. or the Murray Chris-Craft Sportdecks Inc. Limited Warranty prior to the time of purchase of my Chris-Craft boat.

I UNDERSTAND THAT THE WARRANTY BECOMES EFFECTIVE UPON THE DATE OF PURCHASE BY ME OF THE CHRIS-CRAFT BOAT DESCRIBED IN THIS REGISTRATION CERTIFICATE, AND THAT I MUST COMPLETE, SIGN AND RETURN THIS REGISTRATION CERTIFICATE TO CHRIS-CRAFT WITHIN 15 DAYS OF SALE OF SUCH BOAT TO ME AS A CONDITION PRECEDENT TO OBTAINING ANY COVERAGE UNDER THIS LIMITED WARRANTY. I UNDERSTAND THAT THERE IS NO OTHER WARRANTY PROVIDED BY CHRIS-CRAFT REGARDING MY CHRIS-CRAFT BOAT.

I have received a copy of and have read the Federal Boating Safety Information provided by Chris-Craft.

I UNDERSTAND THAT IF I FAIL TO COMPLETE AND RETURN THIS WARRANTY REGISTRATION CERTIFICATE CHRIS-CRAFT WILL NOT BE ABLE TO GIVE NOTIFICATION TO ME WHICH IS DESCRIBED IN SAID FEDERAL BOATING SAFETY INFORMATION AND I WILL WAIVE ANY RIGHT TO NOTIFICATION AND/OR REPAIR AT CHRIS-CRAFT'S EXPENSE OF ANY UNSAFE CONDITION WHICH NOTIFICATION AND/OR REPAIR MIGHT OTHERWISE BE REQUIRED BY FEDERAL BOATING LAWS.

Name William H. & Ellen T. Vaseliou  
(Purchaser)

Address 7817 Maplewood Dr. #608

City and State Melbourne, FL 32935

Signature [Signature]

RECEIVED JAN 6 1986

RECEIVED DEC 6 1985  
09 334 1

Model 266 Year 86

Hull No. \_\_\_\_\_

Port Engine No. A 485777

Starboard Engine No. \_\_\_\_\_

Date of Purchase November 18, 1985

SELLING DEALER

Name Skyline's Anchorage Yacht

Address 96 E. Eau Gallie Blvd. Basin

City and State Melbourne, FL 32937

Signature [Signature]

Salesman Laminic Mine

NEW BOAT — 12 MONTHS LIMITED WARRANTY COVERAGE.

DEMONSTRATOR BOAT — MONTHS LIMITED WARRANTY COVERAGE REMAINING TO FIRST PURCHASER. PLACED INTO DEMO SERVICE ON \_\_\_\_\_

RECEIVED MAR - 7 1986

*Chris + Craft*

266-122

DEALER (IMPRINT CARD) *093344*  
 Skyline's Indian Harbour Marina  
 1399 Banana River Drive  
 Indian Harbour Beach, Fl. 32937

MURRAY  
**WARRANTY CLAIM FORM**  
 P.O. Box 9450  
 Bradenton, FL 33506  
 Phone 753-8951

OWNER (IMPRINT CARD)  
 #698  
 Melbourne, Fl. 32935

*9-12-86*  
*091113*  
*18999*

CLAIM NO. 1063  
 BOAT MODEL 266 AC  
 HULL NO. —  
 REGISTRATION DATE 11-18-83  
 HOURS OPERATION —  
 LABOR RATE \$24.00

DESCRIPTION OF WARRANTY REPAIR

PARTS FOR CREDIT

PARTS PRICE

LABOR HOURS

1) Remove cracked lexan hatch (doorway).

Install new companionway door plex  
*\$250.00 according to spec*  
*parts 3-22-86 see attached letter*

UPS fgt.

2.89

1.5

Comp. door lexan  
 12 x 36

~~350.00~~  
250.00

36

CODE 404

2) Install new forward hatch latch

Original was missing.

1 - P100-09

dog bolt

22.20

.5  
 12

CODE 404

3) Remove and replace cracked bow pulpit

per phone conversation with Rick Pruitt.

Original bow pulpit was sent 3/6/86

Caulk

9.85

Teak bow pulpit  
 P.O. 2031

148.50

3.0  
 72  
 120

CODE 404

WARRANTY CLAIM REPORT

TOTALS OF WARRANTY REQUESTED

\$433.44 5.0

THIS FORM MUST BE FILLED IN COMPLETELY AND SUBMITTED WITHIN 30 DAYS OF COMPLETION OF WORK. *553.44*

I hereby affirm that the repair indicated has been satisfactorily completed and that the owner of the boat identified above has not been and will not be charged for repair costs represented by this Warranty Claim, or if already so charged will be refunded the full amount of credit allowed to me hereby; further, that no other claim has been made nor will be made by any member of my organization for reimbursement for repair represented by this claim.

Owner Signature

Dealer Signature *J. Curless*

Date 3-6-86

DO NOT WRITE BELOW THIS LINE (FOR COMPANY USE ONLY)

PARTS RECEIVED BY \_\_\_\_\_ DATE \_\_\_\_\_  
 CREDIT ISSUED TO \_\_\_\_\_ DATE \_\_\_\_\_  
 REVIEWED BY *[Signature]* DATE 8/21/86  
 APPROVAL BY *[Signature]* DATE \_\_\_\_\_

INVOICE PARTS 433.44  
 DEALER PARTS \_\_\_\_\_  
 DEALER LABOR 120.00  
 SUB LABOR \_\_\_\_\_  
 FREIGHT \_\_\_\_\_

TOTAL CREDIT ALLOWED 553.44

PLANT \_\_\_\_\_

White — Customer Service Copy

Canary — Memo

Pink — Dealer File Copy

Goldenrod — Return Parts List

Form 1075

*20* *115*

AMOUNT	DESCRIPTION
9.85	11K
82.120	09 Built
850.-	Comparison by Dozer
	12 X 36
148.50	Talk Buss
	180060213-18
	Reliant

*Warrant claim 3-6-86*  
*Warrant Head g.*  
*UPS 2 89*

*No warranty*

ANCHORAGE INDIAN HARBOR  
YACHT BASIN  
96 East Bay Galile Causeway  
Melbourne, Florida 32937  
(305) 773-1818

MARINA  
1990 Bayview River Drive  
Indian Harbour Beach, Florida 32937  
(305) 773-2400

DRAGON POINTE MARINAS  
*Valover*

DATE 1/20/86 - 36-86  
NUMBER 1063

DATE 1/20/86  
BUSINESS PHONE 772-3244  
CITY VALOVER  
STATE FLA  
ZIP 32909

MAKE CHRYSLER  
MODEL 266 AC  
YEAR 1986  
SIZE 286  
HULL NO. 550  
FIBERGLASS

REPAIR ORDER INSTRUCTIONS CHARGE ( ) CUSTOMER ( ) WARRANTY

NOTE: APPLIED TO W/O 68089 - 76 2008

1) REPAIRS CANCELED LEAN HARK  
2) REPAIRS CANCELED BOU POLLEY  
3) ~~REPAIRS CANCELED~~ *WARRANT CLAIM*  
*3) install powerhead parts*

SERIAL NO. ENGINE NO. 1  
SERIAL NO. DRIVE NO. 2  
SERIAL NO. ENGINE NO. 1  
SERIAL NO. DRIVE NO. 2

UP 5 2.89  
5405 @ 24.-  
130.-

ALL WORK CASH ON DELIVERY

Launch  Haulout  Pickup  Delivery

BASES FOR CHARGES  
 HOURLY RATE  
 DAY RATE  
 BOTH

CUSTOMERS INTENDED METHOD OF PAYMENT  
 CASH  
 CHECK  
 CREDIT CARD

WE SIGNATURE HERE IN AS FOLLOWS  
I AM AUTHORIZED TO SIGNIFY THAT THE WORK HAS BEEN COMPLETED TO MY SATISFACTION

CHARGES  
LABOR CHARGES

TERMS CASH CHARGE INTERNAL

PAY THIS AMOUNT \$ 553.44

TOTAL LABOR 120.-  
TOTAL PARTS 430.55  
TOTAL 550.55  
TOTAL 553.44

RECEIVED MAR - 7 1986

Chris Craft

626-122

DEALER (IMPRINT CARD)  
Skyline's Indian Harbour Marina  
1399 Banana River Drive  
Indian Harbour Beach, Fl. 32937

MURRAY WARRANTY CLAIM FORM

P.O. Box 9450  
Bradenton, FL 33506  
Phone 753-8951

181000

OWNER (IMPRINT CARD)  
Melbourne, Fl. 32935

CLAIM NO. #68089  
BOAT MODEL 266 AC  
HULL NO. 5 BF 122  
REGISTRATION DATE  
HOURS OPERATION  
LABOR RATE 224.00 20.00

DESCRIPTION OF WARRANTY REPAIR	PARTS FOR CREDIT	PARTS PRICE	LABOR HOURS
1) Door locks (companionway) not adjusted properly. We fabricated brackets so lock could be opened more easily. 401 Reg Amt 16.00 16.00 1920 1920	401		.8
2) Shower sump pump was inoperative. Put in float switch, tested. Problem solved. 301 Reg Amt 15.00 15.00 1802 1809	301		.75
3) Found oil leak at steering helm - liquifying grease drainage. Traced problem area. Sealed helm head. Leak stopped. 201 Reg Amt 20.00 20.00 2400 2400	201		1.0
4) Cabin light switch at helm was inoperative. Found loose wire and re-connected. 304 Reg Amt 4.00 4.00 480 480	304		.2

WARRANTY CLAIM REPORT

TOTALS OF WARRANTY REQUESTED  
SUBMITTED WITHIN 30 DAYS OF COMPLETION OF WORK.

2.75  
616.00

I hereby affirm that the repair indicated has been satisfactorily completed and that the owner of the boat identified above has not been and will not be charged for repair costs represented by this Warranty Claim, or if already so charged will be refunded the full amount of credit allowed to me hereby; further, that no other claim has been made nor will be made by any member of my organization for reimbursement for repair represented by this claim.

Owner Signature \_\_\_\_\_ Dealer Signature J. Curless Date 3/6/86

DO NOT WRITE BELOW THIS LINE (FOR COMPANY USE ONLY)

PARTS RECEIVED BY _____	DATE _____	INVOICE PARTS _____
CREDIT ISSUED TO _____	DATE _____	DEALER PARTS 55.00
REVIEWED BY _____	DATE _____	DEALER LABOR _____
APPROVAL BY Ed Rant	DATE 3-27-86	SUB LABOR _____
PLANT _____		FREIGHT _____
		TOTAL CREDIT ALLOWED 5500

## DEALER (IMPRINT CARD)

Skyline's Indian Harbour Marina  
1398 Banana River Drive  
Indian Harbour Beach, Fl. 32937

MURRAY

Chris + Craft®

## WARRANTY CLAIM FORM

P.O. Box 9450  
Bradenton, FL 33506  
Phone 753-8951

## OWNER (IMPRINT CARD)

N/A

CLAIM NO. #2604  
BOAT MODEL 230  
HULL NO. 6151  
REGISTRATION DATE  
HOURS OPERATION  
LABOR RATE 524.00

## DESCRIPTION OF WARRANTY REPAIR

## PARTS FOR CREDIT

## PARTS PRICE

## LABOR HOURS

Install trim harness for Mercuriser 230. Harness was installed incorrectly from factory. Put boat in water to check rattling noise. Had to lift boat and pull off drive unit. Checked alignment and could not get the alignment tool into splines.

CODE

Mechanics notes: "Pulled motor out of boat. Had to remove half the boat and one manifold to get it out. Had to grind and cut off one inch of motor head."

mask	.60	
60 grit paper	2.95	
rubber gloves	.50	1.75
small buckets	.90	
1" brush	.75	

CODE em. Bottle 100 1.00

Reinstall engine, rearmount mounts, install port side manifold, install power steering pump, install drive unit, hook up miscellaneous hoses, cables, and make necessary adjustments. Problem solved.

1 qt. Dexton	1.90	
1 gasket set	8.95	
2 - 2" clamps	2.30	

CODE

CODE

## WARRANTY CLAIM REPORT

THIS FORM MUST BE FILLED IN COMPLETELY AND SUBMITTED WITHIN 30 DAYS OF COMPLETION OF WORK.

TOTALS OF WARRANTY REQUESTED

207.35 10.5

I hereby affirm that the repair indicated has been satisfactorily completed and that the owner of the boat identified above has not been and will not be charged for repair costs represented by this Warranty Claim, or if already so charged will be refunded the full amount of credit allowed to me hereby; further, that no other claim has been made nor will be made by any member of my organization for reimbursement for repair represented by this claim.

Owner Signature

Dealer Signature

Date

4-16-86

DO NOT WRITE BELOW THIS LINE (FOR COMPANY USE ONLY)

PARTS RECEIVED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CREDIT ISSUED TO \_\_\_\_\_ DATE \_\_\_\_\_  
REVIEWED BY \_\_\_\_\_ DATE \_\_\_\_\_  
APPROVAL BY \_\_\_\_\_ DATE \_\_\_\_\_

INVOICE PARTS  
DEALER PARTS  
DEALER LABOR  
SUB LABOR  
FREIGHT

TOTAL CREDIT ALLOWED

PLANT



MURRAY

Chris-Craft®

Sportboats Inc.

Bradenton, Florida 33506

(813) 755-1544

10/7

NO 7084

QUALITY CONTROL AND EQUIPMENT CHECK LIST

Dealer: <b>SKYLINE'S ANCHORAGE</b>		Dealer City: <b>MELBOURNE FL</b>	
Boat Model: <b>266</b>	Serial Number:	Deck Color: <b>TAUPE</b>	Hull Color: <b>GRAND</b>
Invoice No.:	No. of battery:	Engine Make: <b>MERC</b>	H.P.: <b>260</b>
		Engine Port & Starboard: <b>A 48 277 6822846</b>	
		Outdrive Port & Starboard: <b>A 48049</b>	

ITEM-DESCRIPTION	ITEM-DESCRIPTION	ITEM-DESCRIPTION
<b>SAFETY GROUP</b>	Deck feature stripe	Stainless-sink
Foam flotation	Convertible top cover	Icebox
Kill switches	Rod holders	Water tank-gallon <input type="checkbox"/>
Bilge pump	Bow rider cushion	Water tank-20 gallon <input type="checkbox"/>
Bilge blower		Bunk cushions
Navigation lights	<b>INSTRUMENTATION</b>	Am/FM stereo cassette
Engine compartment lights	Compass	Table & leg
Courtesy lights	Speedometer	Wine rack
Spot light	Tachometer	Door curtains, 4
<b>SAFETY INSPECTION</b>	Engine-hour meter	Drapery package
<b>FUEL SYSTEM</b>	Fuel gauge	Mirror
1. Hose clamps installed	Amperage gauge <b>100-15</b>	Alcohol stove
2. Flex line hooked up	Oil pressure gauge	Electric alcohol stove
3. Vent clear	Temperature gauge	<b>CANVAS GROUP</b>
4. Identification plate clear	Firm indicator gauge	Upside/aft curtains
5. Wires hooked up	Mechanical steering & wheel	Top with full camper
6. Pressure check	Switch & fuse panel	Bimini top with full enclosure
7. Filler & hose tight, vent on hose tight	Cigarette lighter	Soft top only
<b>ELECTRICAL SYSTEM</b>	ABS panels	Upside curtains
1. Navig. lights, blower, pump, horn	<b>COCKPIT GROUP</b>	Shipping covers
2. Trim & tilt, neutral safety switch	Redstart seats <b>HELM SEAT</b>	Cockpit cover
3. Battery cables & tiedown	Lounge seats	Bow cover
<b>VENTILATION SYSTEM</b>	Bucket seats	<b>FINISH</b>
1. Hoses secured and clear	Engine box cushion	Deck
2. Blower hooked up and free	Rear sliding seats	Hull
<b>WARNING DECALS</b>	Rear lounge-double bed	Liner
1. Coast Guard Capacity	Vinyl inspection	Clean
2. Blower warning	Under-deck storage	<b>ENGINE GROUP</b>
3. Fuel system	Coaming panels	Props Alum <input checked="" type="checkbox"/> S S prop <input type="checkbox"/> <b>4.7</b>
4. Battery caution	Teak trim	Engine warranty & keys
5. Propeller warning	Starboard seat with wet bar	Oil level
<b>STEERING SYSTEM</b>	Indoor/outdoor carpet	Anti-freeze
1. Back & helm secure	Igloo cooler, 86 quart	Engine drain plugs rem. frm. bck.
2. Steering arm tight—lock nut installed	Igloo cooler, 151 quart	O/B kit
3. Cable centered on drum	Teak rod-holders	Cooling-hoses installed
4. Wheel free full left and right	Teak storage compartment	Fuel line installed
<b>CONTROLS</b>	Grab bar	Flame arrester tight
1. Shift cable/wires secure	Engine box <b>HATCH w/ SUBDRI</b>	<b>SPECIAL ITEMS / COMMENTS</b>
2. Throttle cable secure	Fiberglass liner	Iron paint
3. Neutral switch operative	Drain holders, plexiglass	<b>HOT WATER HEATER</b>
<b>HULL GROUP</b>	Battery & case	<b>WET BENCH SEAT</b>
Bow eyes	Cockpit galley	<b>BATTERY BOASTER</b>
Stern eyes	Battery switch	<b>BATTERY CHARGER W/</b>
Portlight	Sundeck pad	<b>W/ BERTH COUPLER</b>
Hull feature stripes	Extra battery & switch	
Teak swim platform <b>GLASS</b>	<b>CABIN GROUP</b>	
Hydraulic Benet	Teak cabin door with <b>hosp LOCK</b>	
Hydraulic trim tabs—Mercury	Hanging locker door	
Drain plug	Rope-locker cover door	
Three/ tone gelcoat	Companionway hatch	
<b>DECK GROUP</b>	Porta Potti	<b>BOAT OWNER'S ENVELOPE</b>
Bow cleats	Handy-head (self-contained)	Boat Owner's Manual
Stern cleats	Shower curtain	Engine Manual
Box chocks	Shower (hot water)	Accessory Instructions
Step pads-tek	Headliner inspection	Inspector: <b>W. J. ... 920-85</b>
Bow lifting ring	Cabin lights	Shipping Date:
Stainless-bow rail	Dinette table	
Forward hatch	Refrigerator (12V/110V)	
Tempered glass windshield	110V shore power	
Sliding side windows	Water pressure system	
Windshield wiper	Shore power cord	
Horn	Cabin galley	

— NO CLAIMS HONORED UNLESS NOTED HEREON —

Above boat and equipment received in good condition except as otherwise indicated.

Dealer: **M. N. ...**

Date: **10-1-85**